

CITGO Lemont WESP Turnaround Inspection Photograph Log

September 2010

1. Overall view of top of WESP showing the electrodes, stud bolts/hangers, and honeycomb cells
2. Broken electrode hanger stud bolt
3. Broken electrode hanger stud bolt
4. Broken electrode resting on the distribution tray

1. Overall view of top of WESP showing the electrodes, stud bolts/hangers, and honeycomb cells



H-2

ENFORCEMENT CONFIDENTIAL – DO NOT RELEASE
MAY CONTAIN INFORMATION CLAIMED AS CBI

2. Broken electrode hanger stud bolt



H-3

ENFORCEMENT CONFIDENTIAL – DO NOT RELEASE
MAY CONTAIN INFORMATION CLAIMED AS CBI

3. Broken electrode hanger stud bolt



H-4

ENFORCEMENT CONFIDENTIAL – DO NOT RELEASE
MAY CONTAIN INFORMATION CLAIMED AS CBI

4. Broken electrode hanger stud bolt



H-5

ENFORCEMENT CONFIDENTIAL – DO NOT RELEASE
MAY CONTAIN INFORMATION CLAIMED AS CBI